



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Report Date July 20, 2006

Supervisor DRH

Mine Name: Promontory Point West
Operator Name: Kerry's Inc

Permit number: S0030057
Inspection Date: 07/18/2006
Time: Morning

Inspector(s): Dan Smith
Other Participants: None
Mine Status: INA

Weather:

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

GPS site to get acreage amounts.

Directions to Site:

Site is easily accessed from Promontory Point road. Locked gate is approx. 1 mile from site.

Inspection Summary:

Unable to access site due to locked gate.

Conclusions and Recommendations:

Site acreage was obtained by screen digitizing and is very large (25.39 acres). Accurate GPS readings need to be taken to determine correct acreage amounts. Recommend that the primary inspector review this site.

Inspector's Signature Daniel Smith

Date: July 20, 2006

ds

cc: Kerry's Inc

Attachment: Map & Photos



07.18.2006 10:33



Mine Number: S0030057
Mine Name: Promontory Point West
Township 06 N Range 06 W Section 14 SLBM

Inspection Date July 18, 2006
Map Produced by DKS

Acres Disturbed	25.39 (Screen Digitized)
Acres Regraded	0
Acres Seeded	0
Road Acres Disturbed	0
Total Acres Disturbed	25.39
Acres Released	0
Acres Excluded	0
Acres PreExisting	0
Acres Prelaw	0

- Legend
All items symbolized in legend may not be appear on map
- County Boundary
 - Access
 - Mine
 - NonMine
 - Reclaimed
 - Other
 - Interstate
 - US Route
 - State Route
 - Primary Route
 - Secondary Route
 - Main Dirt Road
 - Unimproved Road
 - Interchange
 - Trail
 - Section line
 - Section line: location doubtful
 - Township or range line
 - Township or range line: location doubtful
 - Disturbed
 - Regraded
 - Seeded
 - Released
 - Excluded
 - PreExisting
 - Prelaw
 - Bond Area
 - SITLA Mineral Leases
 - BLMSaleMinerals
 - Community/PI
 - SITLA Mineral Ownership

DOQ imagery date 1993



Dept. of Natural Resources
Division of Oil, Gas, and Mining
Mineral Mines Program

Different data sources and input scales
may cause misalignment of data layers.
This product may not meet DOGM
standards for accuracy and content.

